

AD-A145 241


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
NORTHFIELD SCHOOL UPP..(U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV APR 81


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A145 241

CONNECTICUT RIVER BASIN  
NORTHFIELD, MASSACHUSETTS

1

NORTHFIELD SCHOOL UPPER RESERVOIR DAM  
MA 00051

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

DTIC FILE COPY



DTIC  
ELECTE  
SEP 5 1984  
D

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154

APRIL 1981

DISTRIBUTION STATEMENT

Approved for public release  
Distribution Unlimited

84 09 05 080

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00051	2. GOVT ACCESSION NO. AD-A145241	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Northfield School Upper Reservoir Dam  NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS	5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT	
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	8. CONTRACT OR GRANT NUMBER(s)	
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	12. REPORT DATE April 1981	
	13. NUMBER OF PAGES 65	
	15. SECURITY CLASS. (of this report)  UNCLASSIFIED	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report)  APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Northfield, Massachusetts		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Northfield School Upper Reservoir Dam is a 45 year old earth embankment dam. The dam is approximately 240 feet long and has a maximum height of about 37 feet. The dam appears to be in fair overall condition. The recommended range of the test flood for a "Small" size, "Significant" hazard dam is from the 100-year flood to ½ the PMF.		



DEPARTMENT OF THE ARMY

NEW ENGLAND DIVISION  
424 BRATTLE STREET  
WALTHAM, MASSACHUSETTS 01901

NEDED

Honorable Edward J. King  
Governor of the Commonwealth of  
Massachusetts  
State House  
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Northfield School Upper Reservoir Dam (MA-00051) Phase I Inspection Report, prepared under the National Program for Inspection of Non-Federal Dams. This report is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. I approve the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is vitally important.

Copies of this report have been forwarded to the Department of Environmental Quality Engineering, and to the owner, Northfield - Mt. Barnard School, Physical Plant Office, East Northfield, MA. Copies will be available to the public in thirty days.

I wish to thank you and the Department of Environmental Quality Engineering for your cooperation in this program.

Sincerely,

Incl  
As stated

C. E. EDGAR, III  
Colonel, Corps of Engineers  
Commander and Division Engineer

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
By	
Date	
Dist	
A/1	

NORTHFIELD SCHOOL UPPER RESERVOIR DAM  
MA 00051



CONNECTICUT RIVER BASIN  
NORTHFIELD, MASSACHUSETTS

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

## NATIONAL DAM INSPECTION PROGRAM

### PHASE I INSPECTION REPORT

Identification No:	MA 00051
Name of Dam:	Northfield School Upper Reservoir Dam (Grandin Reservoir Dam)
Town:	East Northfield
County and State:	Franklin County, Massachusetts
Stream:	Louisiana Brook
Date of Inspection:	December 4, 1980

### BRIEF ASSESSMENT

Northfield School Upper Reservoir Dam is a 45-year old earth embankment dam which impounds water for the Northfield - Mt. Hermon School and the Town of East Northfield. The dam is approximately 240 feet long and has a maximum height of about 37 feet. The slope of the upstream face of the dam is about 2.5 H:1V, the top width is approximately 17 feet and the slope of the downstream face is approximately 2H:1V. A gatehouse located on the top of the dam provides access to outlet works for the dam.

The dam appears to be in fair overall condition. No obvious signs of settlement or misalignment are evident; however, clear seepage and erosion are apparent at each of the abutments and at the toe of the dam. Lack of a comprehensive operation and maintenance program is also apparent, as evidenced by the presence of small trees and brush on the dam and large trees in close proximity to the dam. In addition, only one of the outlet valves was found to be operable. (Since the date of inspection, the Owner has notified us that all of the valves have been made operable).

Northfield School Upper Reservoir Dam has a maximum capacity of approximately 104 acre-feet and a maximum height of about 37 feet. These values fall within the ranges specified by the Army Corps of Engineers for "Small" size dams. If Northfield School Upper Reservoir Dam were to fail, it is anticipated that appreciable property damage would result at the hazard area located approximately 0.6 mile downstream of the dam, along with the possible loss of a few lives. Therefore, the hazard classification is "Significant". The recommended range of the test flood for a "Small" size, "Significant" hazard dam is from the 100-year flood to one-half of the Probable Maximum Flood (PMF). Because the height of the dam is close to the upper limit established for "Small" size dams, and because of the potential for appreciable property damage, the selected test flood for the dam assessment is one-half of the PMF.

The test flood peak inflow to Northfield School Upper Reservoir Dam was computed to be approximately 550 cfs. The corresponding outflow was also 550 cfs and resulted in a 0.5 foot depth of flow over the dam. The spillway (with the

flashboards in place) has a discharge capacity of about 180 cfs, or roughly 33 percent of the routed test flood outflow, assuming the reservoir pool is at the top of the dam. Assuming the flashboards are removed or fail prior to overtopping of the dam, the spillway capacity would then be approximately 790 cfs or about 44 percent in excess of the routed test flood outflow.

Within one year after receipt of this Phase I Inspection Report, the Owner, the Northfield-Mt. Hermon School, should retain the services of a qualified, registered professional engineer, experienced in the design and construction of dams, to: 1) investigate the source and nature of clear seepage observed along the downstream side abutment areas and at the toe of the dam eroded areas at these locations should be filled, regraded and reseeded; 2) perform a detailed hydraulic/hydrologic analysis to assess the need for increasing the spillway capacity; 3) direct the removal of trees and their root systems from the embankment and the area to within 20 feet of the toe, including the backfilling of any remaining voids with suitable, thoroughly compacted material; and 4) design and direct the installation of control facilities at the inlets of the mid and low level outlets.

In addition, the Owner should implement the following operation and maintenance procedures: 1) initiate a comprehensive operation and maintenance program, designed to ensure the safe and reliable operation of all operating facilities; 2) initiate a program of annual technical inspection; 3) verify the operability of all outlet valves; 4) remove the flashboards from the spillway; 5) monitor the seepage areas identified in this Report, until such time that an engineer can perform the analyses discussed above; and 6) develop a formal surveillance and downstream warning system.

O'BRIEN & GERE ENGINEERS, INC.


JOHN JAY  
WILLIAMS  
No. 30208 (CIVIL)


John J. Williams, P.E.  
Vice President  
Massachusetts Registration No. 30208


Date: 10-1-1967




This Phase I Inspection Report on Northfield School Upper Reservoir Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgement and practice, and is hereby submitted for approval.

  
JOSEPH W. FINEGAN, JR. MEMBER  
Water Control Branch  
Engineering Division

  
ARAMAST MAHTESIAN, MEMBER  
Geotechnical Engineering Branch  
Engineering Division

  
CARNEY M. TERZIAN, CHAIRMAN  
Design Branch  
Engineering Division

APPROVAL RECOMMENDED:

  
JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation: however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

## TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

## REPORT

### 1 PROJECT INFORMATION

1. General	1-1
a. Authority	1-1
b. Purpose	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of Dam and Appurtenances	1-2
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-3
g. Purpose of Dam	1-3
h. Design and Construction History	1-3
i. Normal Operating Procedures	1-3
1.3 Pertinent Data	1-3
a. Drainage Area	1-3
b. Discharge at Damsite	1-3
c. Elevation	1-4
d. Reservoir Length	1-4
e. Storage	1-5
f. Reservoir Surface Area	1-5
g. Dam Data	1-5
h. Diversion and Regulating Tunnel	1-5
i. Spillway	1-5
j. Regulating Outlet	1-6

## TABLE OF CONTENTS (Cont.)


<u>SECTION</u>	<u>PAGE</u>
2. ENGINEERING DATA	
2.1 Design	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
a. Availability	2-1
b. Adequacy	2-1
c. Validity	2-1
3. VISUAL INSPECTION	
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-1
d. Reservoir Area	3-2
e. Downstream Channel	3-2
3.2 Evaluation	3-2
4. OPERATION AND MAINTENANCE PROCEDURES	
4.1 Operation Procedures	4-1
a. General	4-1
b. Description of Any Warning System in Effect	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-2

## TABLE OF CONTENTS (Cont.)

<u>SECTION</u>	<u>PAGE</u>
6. STRUCTURAL STABILITY	
6.1 Visual Observations	6-1
6.2 Design and Construction Data	6-1
6.3 Post Construction Changes	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-2
7.4 Alternatives	7-2

## APPENDICES


APPENDIX A - INSPECTION CHECKLIST	A-1 to A-9
APPENDIX B - ENGINEERING DATA	B-1 to B-20
APPENDIX C - PHOTOGRAPHS	C-1 to C-5
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1 to D-19



UPSTREAM OVERVIEW OF DAM FROM THE SOUTH ABUTMENT. (12/4/80)



DOWNSTREAM OVERVIEW OF DAM FROM THE SOUTH ABUTMENT (12/4/80)



# NATIONAL DAM INSPECTION PROGRAM

## PHASE I INSPECTION REPORT

### SECTION 1

#### PROJECT INFORMATION

##### 1.1 General

a. Authority. The National Dam Inspection Act (Public Law 92-367) was passed by Congress on August 8, 1972. Under this Act, the Secretary of the Army was authorized to initiate, through the Corps of Engineers, the National Program for Inspection of Dams throughout the United States. Responsibility for supervising inspection of dams in the New England Region has been assigned to the New England Division of the Army Corps of Engineers.

O'Brien & Gere Engineers, Inc. has been retained by the New England Division to inspect and report on selected non-federal dams in Massachusetts. Authorization and Notice to Proceed were issued to O'Brien & Gere by a letter dated November 12, 1980 and signed by Col. William E. Hodgson, Jr. Contract No. DACW-33-81-C-0016 has been assigned by the Corps for this work.

b. Purpose. The purpose of inspecting and evaluating non-federal dams is to:

1. Identify conditions which threaten public safety and make the Owner aware of any deficiencies so that he may correct them in a timely manner;
2. Encourage and prepare the Commonwealth to initiate an effective dam safety program for non-federal dams as soon as possible; and
3. Update, verify and complete the National Inventory of Dams.

1.2 Description of Project (Information for the dam was obtained from the Northfield-Mt. Hermon School, Physical Plant Office and the Massachusetts Department of Environmental Quality Engineering.)

a. Location. Northfield School Upper Reservoir Dam (Grandin Reservoir Dam) is located on Louisiana Brook in the Town of Northfield, Massachusetts. Louisiana Brook originates approximately 1.2 miles southeast of the dam and continues in a westerly direction for a distance of approximately 1.6 miles downstream of the dam. At this point, it drains to Pauchaug Brook which flows in a southwesterly direction for another 0.4 mile to the Connecticut River. To illustrate the location, a portion of the USGS quadrangle map entitled "Northfield, Mass. - N.H. - VT." has been reproduced and included as Figure 1 on page vi of this Report. USGS reference coordinates for this dam are N42°43.2' and W72°25.3'.



b. Description of Dam and Appurtenances. Northfield School Upper Reservoir Dam is a 45-year old earth embankment structure with a concrete core wall. It is approximately 240 feet long and has a maximum height of about 37 feet. The upstream face of the dam is on a slope of about 2.5 H:1V. It is covered with hand-placed riprap to within approximately 1.5 feet of the dam crest. A moderate growth of grass, light brush, and small trees cover the 17-foot wide dam crest and downstream slope of the dam. The downstream face is predominantly sloped at 2H:1V from the dam crest to the tree-covered toe of the dam. The main controls for the dam outlets are housed in a small wooden gatehouse located on the dam crest approximately 90 feet from the northern dam abutment.

A 30-foot wide spillway channel is located at the southern dam abutment. It has an 18-foot long by 30-foot wide approach apron and 2.5-foot high permanent wooden flash boards at the spillway inlet (see photo No. 4, Appendix C). The discharge chute, like the approach apron, has an inlaid stone bottom and concrete training walls. As illustrated on page B-1 of Appendix B, the spillway discharge chute is directed northwesterly and tapers to a 15-foot wide channel prior to discharging into Louisiana Brook approximately 90 feet downstream of the spillway inlet. Also, toward the lower portion of the discharge chute, the outside training wall changes from concrete to stone masonry.

The outlet works for the dam consists of: 1) a 14-inch diameter water supply main, which feeds a small holding reservoir approximately 700 feet downstream of the dam; 2) an 8-inch diameter drain originating at a tee connection to the 14-inch water main about 25 feet downstream of the dam; and 3) a 14-inch diameter low level drain which outlets into Louisiana Brook just downstream of the dam. Two 14-inch diameter pipes with gate valves are used to draw water from Elev. 665 and Elev. 655 in the reservoir to convey water to the supply main. (See page B-3, Appendix B). In addition, two 4-inch diameter pipes emerge from the ground about 10 feet downstream from the outlet of the spillway discharge chute at about Elev. 663 (See Sheet A, Appendix C). The origin of these pipes is not known, but it is suspected that they are part of the toe drain system of the dam.

c. Size Classification. Northfield School Upper Reservoir Dam has a maximum storage capacity of 104 acre-feet and a maximum height of about 37 feet. Because these values lie within the 50 to 1,000 acre-feet storage and 25 to 40 feet of height ranges specified by the Army Corps of Engineers for small size dams, Northfield School Upper Reservoir Dam is classified as "Small".

d. Hazard Classification. Flow resulting from an assumed failure of Northfield School Upper Reservoir Dam would be routed via Louisiana Brook to a residential area located approximately 0.6 mile west of the reservoir. Based upon computer analysis of a hypothetical breach of the dam, it is estimated that one house would experience flooding to a depth of one to two feet above its first floor elevation. It is likely that appreciable damage would result at the house, along with the possible loss of a few lives. Northfield School Upper Reservoir Dam is therefore classified as a "Significant" hazard structure.

e. Ownership. The dam is owned by the Northfield-Mt. Hermon School; Physical Plant Office; East Northfield, Massachusetts. (Tel: 413/498-5311)

f. Operator. Responsibility for operation of the dam is assigned to Mr. David Jakuboski, Director of Physical Plant. Mr. Wayne Black, Superintendent of the Water Department, is involved with the daily operation of the dam and its controls.

g. Purpose of the Dam. The dam was originally constructed to provide a water supply for the Northfield-Mt. Hermon school. Currently, the dam impounds water for a total of approximately 700-800 people at the school and approximately 1,500 people in the Town of East Northfield.

h. Design and Construction History. Northfield School Upper Reservoir Dam was designed in 1933 by Mr. Lewis D. Thorpe of Boston, Massachusetts (see Drawings in Appendix B). Construction was started in 1934 and completed in 1935 by personnel from the Northfield-Mt. Hermon School. Since that time, no major additions to or modifications of the original dam have been made, except for the replacement of the flashboards in the spillway about three years ago.

i. Normal Operating Procedures. The mid-level 14-inch diameter intake gate with an invert at El. 665.0 (shown on page B-3, Appendix B) is normally open while the low level 14-inch diameter intake gate with its invert at El. 655.0 is kept closed. Outflow from the reservoir is controlled by adjusting the opening of the 14-inch diameter gate valves located on the water supply main approximately 35 feet downstream of the dam and at the downstream holding reservoir approximately 700 feet downstream of the dam. In addition, pool elevations for each of the reservoirs are checked daily, but stage records are not kept.

### 1.3 Pertinent Data

a. Drainage Area. The watershed for Northfield School Upper Reservoir Dam includes approximately 0.6 square mile of very steep and forested terrain lying to the east of the dam. No development is permitted within the watershed area. Louisiana Brook is the drainage area's main watercourse.

#### b. Discharge at Damsite.

1. Outlet Works. Two known outlets pass through the dam: a) A 14-inch diameter water supply main originates at the base of the concrete well under the gatehouse at El. 654.5. Water is supplied to the main from two 14-inch diameter intake pipes and gates in the concrete well under the gatehouse with inverts of El. 655.0 and El. 665.0. The water supply main conveys water from the concrete well under the gatehouse to a holding reservoir approximately 700 feet downstream of the dam from which water is discharged to the water distribution system. An 8-inch diameter drain on the water supply main with an outlet invert at about El. 650 is located approximately 25 feet downstream of the dam; and b) a 14-inch diameter low level drain for the reservoir with an inlet invert at El. 656<sup>+</sup> in the concrete well under the gatehouse and an outlet invert at the downstream toe of the dam at El. 650<sup>+</sup> is the other outlet. With the reservoir pool at the top of the dam, this drain is capable of passing approximately 20 cfs. This outlet is not indicated on the proposed plans of the dam, but is shown on the 1975 State inspection report included in Appendix B.

2. Maximum Known Flood At Damsite. No records have been kept.
3. Ungated Spillway Capacity at Top of Dam. The capacity of the spillway, assuming that the flashboards are removed to the spillway crest El. 683.5 and the reservoir pool is at top of dam Elevation 687.5, is 790 cfs. Under similar conditions, except with the flashboards in place, the spillway discharge capacity is approximately 180 cfs.
4. Ungated Spillway Capacity at Test Flood Elevation. The ungated spillway capacity with the flashboards removed, at test flood Elevation 688 is 950 cfs. With the flashboards in place, the spillway capacity at test flood elevation 688 is approximately 280 cfs.
5. Gated Spillway Capacity at Normal Pool. N/A
6. Gated Spillway Capacity at Test Flood Elevation. N/A
7. Total Spillway Capacity at Test Flood Elevation. See 1.3.b.4 above. (Note that the flashboards are not easily removable and that it is questionable as to whether or not the flashboards would fail if overtopping of the dam occurred.)
8. Total Project Discharge at Top of Dam. The total project discharge at top of dam Elevation 687.5, including flow through the one of the 14-inch diameter outlets, is approximately 200 cfs with the flashboards in place and approximately 810 cfs with the flashboards removed.
9. Total Project Discharge at Test Flood Elevation. The total project discharge at test flood Elevation 688, including discharge over the spillway, through the low level outlet and over the dam, is approximately 550 cfs with the flashboards in place and approximately 1,200 cfs with the flashboards removed.

c. Elevation (NGVD)

1.	Steambled at Toe of Dam	650.5+
2.	Bottom of Cutoff	Varies
3.	Maximum Tailwater	Unknown
4.	Normal Pool (with Flashboards)	686.0
5.	Full Flood Control Pool	N/A
6.	Spillway Crest (With Flashboards)	686.0
7.	Spillway Crest (Without Flashboards)	683.5
8.	Design Surcharge (Original Design)	Unknown
9.	Top of Dam	687.5
10.	Test Flood Surcharge	688.0

d. Reservoir Length (Feet)

1.	Normal Pool	800
2.	Flood Control Pool	N/A
3.	Spillway Crest (with Flashboards) Pool	800
4.	Top of Dam Pool	850
5.	Test Flood Pool	880

e. Storage (Acre-Feet)

1. Normal Pool	91
2. Flood Control Pool	N/A
3. Spillway Crest (with Flashboards) Pool	91
4. Top of Dam Pool	104
5. Test Flood Pool	109

f. Reservoir Surface Area (Acres)

1. Normal Pool	7.5
2. Flood Control Pool	N/A
3. Spillway Crest (with Flashboards) Pool	7.5
4. Top of Dam Pool	8.8
5. Test Flood Pool	9.4

g. Dam Data

1. Type	Earth Embankment
2. Length	240 feet
3. Height	37 feet
4. Top Width	17 feet
5. Side Slopes (Upstream)	2.5 H:1V
(Downstream)	2 H:1V
6. Zoning	Impervious material upstream of concrete core wall and pervious material downstream of the concrete core wall
7. Impervious Core	Concrete
8. Cutoff	Extension of impervious concrete wall to tight, impervious foundation material
9. Grout Curtain	None

h. Diversion and Regulating Tunnel

Not applicable.

i. Spillway (with flashboards)

1. Type	Stone Masonry Channel (with flashboards)
2. Length of Weir	30 feet
3. Crest Stone Masonry, Elevation	683.5
4. Top of Flashboards, Elevation	686.0
5. Upstream Channel	30-foot wide approach apron
6. Downstream Channel	30-foot wide chute at entrance, tapers to 15-foot width in a distance of about 90 feet, sloped at 7.5%, cement mortared stone bottom with concrete training walls

j. Regulating Outlets

1. 14-inch diameter Water Main

- a.) Invert Elevation in the concrete well under the Gatehouse 654.5
- b.) Size 14-inch Diameter
- c.) Description Bell and Spigot Cast Iron Pipe
- d.) Control Mechanism Gate Valves (one at Gatehouse and one approximately 30 feet downstream of dam)

2. Reservoir Drain

- a.) Invert Elevation in the concrete well under the Gatehouse 656.0
- b.) Size 14-inch Diameter
- c.) Description Bell and Spigot Cast Iron Pipe
- d.) Control Mechanism Gate Valve (one at Gatehouse)

## SECTION 2

### ENGINEERING DATA

#### 2.1 Design

Design drawings have been reduced and included as pages B-1 through B-4 of Appendix B. According to Mr. Jakuboski, the Owner's representative, no other design information is available.

#### 2.2 Construction

The only available construction information is shown on the drawings included in Appendix B.

#### 2.3 Operation

Under normal operating conditions, water flows by gravity through the 14-inch diameter cast iron mid-level intake pipe to the concrete well under the gatehouse and then to a holding reservoir, located 700 feet downstream of the dam, via a 14-inch diameter cast iron water main. The discharge is controlled by adjusting the opening of one of the gate valves on the water main in order to maintain a relatively constant water level in the holding reservoir. If desired, the operator may close the mid-level gate and draw water from the reservoir via the low level gate. In addition, a 14-inch diameter reservoir drain or an 8-inch diameter drain on the water supply main may be opened for emergency drawdown or maintenance operations. For inverts of the above mentioned pipes, refer to paragraph 1.3.b.

#### 2.4 Evaluation

a. Availability. The drawings included as pages B-1 through B-4 of Appendix B are available from the Director of Physical Plant; Northfield-Mt. Hermon School; East Northfield, Massachusetts. The inspection reports in Appendix B were obtained from the Massachusetts Department of Environmental Quality Engineering.

b. Adequacy. The construction drawings, inspection reports, information obtained from the Owner's representatives and the field inspection, provided adequate information for a Phase I evaluation.

c. Validity. With the exception of the omission of the 14-inch diameter cast iron pipe reservoir drain from the drawings, the information appears to be valid. Where possible, field measurements were made to verify the dimensions indicated on the construction drawings.

## SECTION 3

### VISUAL INSPECTION

#### 3.1 Findings

a. General. Northfield School Upper Reservoir Dam was inspected on December 4, 1980. At that time, the pool elevation was 5.5 feet below the crest of the flashboards in the spillway. According to the Owner's representative, the water level is normally at or near the top of the flashboards. The prolonged dry weather period has been responsible for the unusually low water level. No underwater areas, other than those which could be seen from above the water surface, were inspected.

The observations and comments of the field inspection team are noted on a checklist included as Appendix A of this report.

b. Dam. The dam is located in a heavily forested, mountainous region. The abutments and downstream toe of the dam are overgrown with coniferous trees. A few deciduous trees, including a few saplings growing on the dam crest, may be observed among the large pine and spruce trees which surround the dam and reservoir.

The dam appears to be in fair overall condition. The upstream face of the dam appears to be adequately protected with riprap. No evidence of settlement or significant structural deterioration was observed; however, clear seepage (about 2 gpm in each location) and erosion were observed at the toe of the dam near the outlet of a 6-inch diameter vitrified clay toe drain pipe and at each of the downstream side abutment areas. The 6-inch diameter toe drain pipe was discharging approximately 1 gpm at the time of the inspection. A similar quantity of seepage was observed flowing from a slightly eroded area surrounding the outlet.

The downstream side abutments are each eroded at the seepage areas indicated on Sheet A of Appendix C. Seepage at the north side abutment has created a very soft and slightly eroded area approximately 6 feet wide and 10 feet long. The seepage toward the top of the dam at the south side abutment has created a similar, but more eroded area. The area is approximately 10 feet wide, 20 feet long, and has a 1.5 foot depression at the upstream end, where the embankment has been eroded away.

Several trees, ranging in size up to approximately 12 inches in diameter, were observed growing at the downstream toe of the dam. Further downstream of the dam, near the outlet of the spillway chute, two 4-inch diameter pipes were observed. These pipes were dry at the time of the inspection. The locations of the outlet works are illustrated on Page C-1 of Appendix C.

c. Appurtenant Structures. A wooden gatehouse, which is located on the dam crest approximately 90 feet from the northern dam abutment, provides access to two intake gate operators and one low level outlet gate operator. This arrangement is not desirable, since the outlet pipes upstream of the gatehouse are continuously under pressure. The gatehouse has a 32-foot deep concrete well, which

was observed to have superficial spalling at its exposed exterior corners. To discourage vandalism, windows have not been installed in the gatehouse.

A 30-foot wide spillway is located at the southern dam abutment. The spillway inlet has an 18-foot long by 30-foot wide approach apron, 2.5-foot high wooden flashboards, and a 90-foot long discharge chute which tapers from 30 feet wide to 15 feet wide at its outlet. The entire spillway system is in good condition, except for several trees overhanging the discharge chute and it appears that the flashboards would not fail prior to overtopping of the dam. Several photos of the appurtenant structures are included in Appendix C.

d. Reservoir Area. The watershed consists of approximately 0.6 square miles of steep and forested terrain. Minor erosion could be observed along the tree-lined banks of the reservoir, but no significant accumulations of silt were observed. Development has not been permitted in the watershed area.

e. Downstream Channel. The discharge channel just downstream of the spillway chute leading to Louisiana Brook is free of debris, as shown on photo no. 8 of Appendix C. The brook itself is very small and well defined, but overgrown with brush and trees along its banks. No significant flow restrictions are evident along the channel until it reaches a 4-foot square box culvert at Winchester Road, approximately 3,000 feet downstream of the dam.

### 3.2 Evaluation

The dam is considered to be in fair overall condition. The seepage and erosion areas should be closely monitored, a more comprehensive operation and maintenance program, including periodic removal of brush and trees from the dam and areas in close proximity of the dam, should be instituted, and valves should be installed at the inlets of the mid and low level outlets.



## SECTION 4

### OPERATION AND MAINTENANCE PROCEDURES

#### 4.1 Operation Procedures

a. General. Normal operation includes gravity flow of water from the reservoir via the mid-level 14-inch diameter cast iron intake pipe to the concrete well under the gatehouse. In the well water enters another 14-inch diameter cast iron pipe which conveys the discharge to a holding reservoir located approximately 700 feet downstream of the dam. According to the Operator, a constant level is maintained at the holding reservoir by adjusting the opening of gate valves located on the 14-inch diameter water main. The only other operating procedure consists of checking the daily pool levels; however, stage records are not kept.

b. Description of any Warning System in Effect. According to the Owner's representative, the dam would be monitored during an extended period of rapid snowmelt and/or rainfall. Residents in the downstream hazard area would be notified if the water level approached the top of the dam. No formal warning system has been established.

#### 4.2 Maintenance Procedures

a. General. According to the Owner's representative, maintenance is performed as needed. No formal maintenance program has been established.

b. Operating Facilities. At the time of inspection, only the mid-level intake gate was found to be operable. Since that time, however, the Owner's representative has informed us that all of the valves have been exercised and now appear to be in good condition. No routine maintenance of operating facilities is performed.

#### 4.3 Evaluation

Existing operation and maintenance procedures should be improved through the implementation of a more comprehensive program. Periodic maintenance should be performed to keep the dam clear of extraneous growth and to ensure reliable operation of the outlet works. In addition, a formal downstream warning system should be developed and annual technical inspections by qualified, registered engineers should be performed.

## SECTION 5

### EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

#### 5.1 General

Northfield School Upper Reservoir Dam has a steep, forested, watershed ranging from El. 1319 at Notch Mountain to El. 686 at the normal pool elevation. Louisiana Brook, the main watercourse to the Reservoir, originates approximately 1.2 miles to the southeast of the reservoir and flows in a westerly direction to the reservoir and, ultimately, to the Connecticut River. The normal storage in Northfield School Upper Reservoir is approximately 91 acre-feet.

#### 5.2 Design Data

According to a letter to the State from former Director of Physical Plant, Carl A. Pelzel, the original flashboards in the spillway were designed to fail when a predetermined overtopping depth is experienced. (See pages B-18 and B-19, Appendix B.) However, the current flashboards were constructed approximately three years ago and may not conform to the original design of failing when a predetermined overtopping depth is experienced. No further hydraulic/hydrologic information is available, according to the current Director of Physical Plant.

#### 5.3 Experience Data

Personnel from the Northfield - Mt. Hermon School check the reservoir pool elevation daily, but stage records are not kept.

#### 5.4 Test Flood Analysis

The recommended test flood range for a "Small" size, "Significant" hazard dam is from the 100-year design storm to one-half of the probable maximum flood (PMF). Because the height of the dam is close to the upper limit of 40 feet established for a "Small" size dam and the potential for appreciable property damage at a residence located about 150 feet downstream Winchester Road, the selected test flood is one-half of the PMF.

Hydraulic and hydrologic calculations were performed with the assistance of HEC-1-DB computer program. Flood hydrographs were developed from Snyder unit hydrographs using average coefficients, an initial infiltration value of zero and a constant loss rate of 0.05 inches per hour. The test flood runoff was reduced according to the "Hop Brook" reduction factor<sup>1</sup>, a hypothetical value which takes into account the size of the drainage area and the probability of the storm area coinciding with the drainage area. The routing analysis consisted of constructing the inflow hydrograph for the test flood and routing it over the dam. Stage vs. discharge and stage vs. storage relationships were developed to obtain the outflow hydrograph. The reservoir pool was assumed to be at the crest of the flashboards at the beginning of the test flood storm event.

<sup>1</sup>

Corps of Engineers, Engineering Circular No. 1110-2-27, Aug' 66

The peak test flood inflow to Northfield School Upper Reservoir was computed to be approximately 550 cfs (920 csm). The peak test flood outflow was also 550 cfs and resulted in a 0.5-foot depth of flow over the dam. The spillway (with the flashboards in place) has a discharge capacity of about 180 cfs, or roughly 33 percent of the routed test flood outflow, assuming the reservoir pool is at the top of the dam.

Assuming the flashboards are removed or fail prior to overtopping the the dam, the spillway capacity would then be approximately 790 cfs or about 44 percent in excess of the routed test flood outflow.

#### 5.5 Dam Failure Analysis

Failure of the dam was simulated through the use of the HEC-1-DB computer program. This failure was assumed to be 60 feet wide by 31 feet deep and was initiated when the reservoir pool elevation reached the top of the dam during a 0.13 PMF storm event. The quantity of breach discharge for this size dam is very sensitive to the duration over which the breach is assumed to develop. Therefore, two durations were evaluated: 1) a 15-minute breach and 2) a 1.5-hour breach. For the purposes of this report, breach discharges corresponding to the 15-minute duration breach are discussed. The discharge resulting from the breach was routed along Louisiana Brook for a distance of approximately 0.6 mile to a 4-foot square box culvert under Winchester Road.

Just prior to failure of the dam, a discharge of approximately 260 cfs would be experienced at the Winchester Road culvert. The corresponding pool surface upstream of the road culvert was computed to be at El. 387.8, or just below the road surface. As a result of the simulated dam failure, a peak discharge of 5,490 cfs, with a maximum stage of El. 391.4 was computed at Winchester Road (3.4 feet over the road).

Such a discharge would result in a depth of flow of between one and two feet at a residence located approximately 150 feet downstream of Winchester Road and would cause appreciable property damage, with the possible loss of a few lives. According to Corps criteria, the damage potential for failure of the Northfield School Upper Reservoir Dam places the dam in the "Significant" hazard classification.

## SECTION 6

### STRUCTURAL STABILITY

#### 6.1 Visual Observations

The dam was observed to be in fair overall condition. No obvious signs of settlement or structural movement of the dam were observed. Minor spalling was observed at the corners of the gatehouse, but no structural deficiencies were observed. The interior walls of the gatewell were not examined; however, Mr. Wayne Black, Water Superintendent, believes the walls are in good condition.

Clear seepage was observed at the groin areas of each abutment and at the toe of the dam near the outlet of the 6-inch diameter toe drain pipe. In each location, the seepage was estimated to be about two gallons per minute of clear flow; however, moderate erosion and extremely soft ground conditions were observed at the abutment locations. The area around the toe drain outlet is slightly eroded. The seepage warrants further investigation.

#### 6.2 Design and Construction Data

Plans of the dam and its appurtenances are included in Appendix B. According to Mr. Jakuboski, further information is not available.

#### 6.3 Post Construction Changes

The only known modification was made about three years ago when new flashboards were installed in the spillway. No plans exist for that construction, according to Mr. Jakuboski.

#### 6.4 Seismic Stability

Northfield School Upper Reservoir Dam is located in Seismic Zone 2 on the "Seismic Zone Map of Contiguous States." Therefore, according to the "Recommended Guidelines for Phase I Dam Inspections," the dam need not be evaluated for seismic stability.

## SECTION 7

### ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

#### 7.1 Dam Assessment

a. Condition. From visual inspection, it appears that the dam is in fair overall condition. Potentially serious conditions exist at each of the abutments and at the toe of the dam, where clear seepage (about 2 gpm in each location) and erosion have been observed. The remainder of the dam appears to be structurally sound, but the presence of trees on and close to the dam suggest that maintenance should be performed on a more regular basis. The flashboards at the spillway inlet appear to be permanent and severely restrict the spillway capacity. Infrequent exercising of valves on the outlet works was identified as an operational deficiency.

b. Adequacy of Information. The visual inspection, along with the information provided by the Director of Physical Plant at the Northfield - Mt. Hermon School, and inspection reports provided by the Massachusetts Department of Environmental Quality Engineering, proved adequate for a Phase I evaluation of Northfield School Upper Reservoir Dam.

c. Urgency. The recommendations and remedial measures described in this Section should be implemented within one year of receipt of the Phase I Inspection Report.

#### 7.2 Recommendations

The Owner, the Northfield - Mt. Hermon School, should retain the services of a qualified, registered professional engineer, experienced in the design and construction of dams, to:

1. Investigate the source and nature of the seepage observed along the downstream side abutment areas and at the toe of the dam and recommend appropriate corrective measures. Eroded areas at those locations should be filled, regraded and reseeded.

2. Perform a detailed hydraulic/hydrologic analysis to assess the need for increasing the spillway capacity.

3. Direct the removal of trees and their root systems from the embankment and the area to within 20 feet of the toe and direct the backfilling of any remaining voids with suitable, thoroughly compacted material.

4. Design and direct the installation of control facilities at the inlets of the mid and low level outlets.

Recommendations of the engineer should be implemented by the Owner as soon as practicable.

### 7.3 Remedial Measures

The following operation and maintenance procedures should be implemented by the Owner:

1. Initiate a comprehensive operation and maintenance program, designed to keep the dam free of extraneous growth and ensure the safe and reliable operation of all operating facilities.
2. Initiate a program of annual technical inspection.
3. Verify the operability of all outlet valves.
4. Immediately remove the flashboards from the spillway.
5. Monitor the seepage areas identified in the report, until such time that an engineer can perform the analyses discussed in Section 7.2.
6. Develop a formal surveillance and downstream warning system.

### 7.4 Alternatives

No valid alternatives to the recommendations and remedial measures described above are considered feasible for this site.

APPENDIX A  
CHECKLIST  
VISUAL INSPECTION

VISUAL INSPECTION CHECK LIST

INSPECTION TEAM ORGANIZATION

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)

National I.D.#: MA 00051

Location: Northfield, Massachusetts

Type of Dam: Earth Embankment

Inspection Date(s): December 4, 1980

Weather: Partly Cloudy, Cool

Pool Elevation: 680.5+ NGVD\*

Inspection Team

Lee DeHeer	O'Brien & Gere	Managing Engineer
Leonard Beck	O'Brien & Gere	Structures
Steven Snider	O'Brien & Gere	Foundations & Materials
Alan Hanscom	O'Brien & Gere	Structures
Denis Mehu	Bryant & Associates	Hydrology/Hydraulics

Owner's Representative

Mr. David Jakuboski, Director of Physical Plant;

Northfield School; East Northfield, Massachusetts

(Tel.: 413/498-5311)

\*Estimated from an assumed spillway crest (permanent flashboard) elevation of 686.± indicated on the "Northfield, Mass. - N.H. - Vt." USGS map.



# VISUAL INSPECTION CHECK LIST

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)

National I.D. #: MA 00051

Date(s): December 4, 1980

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	
Crest Elevation	687.5 NGVD
Current Pool Elevation	680.5 NGVD
Maximum Impoundment to Date	Unknown
Surface Cracks	None Observed
Pavement Condition	NA
Movement or Settlement of Crest	None Observed
Lateral Movement	None Observed
Vertical Alignment	Appears to be good
Horizontal Alignment	Appears to be good
Condition at Abutment and at Concrete Structures	Generally, good at spillway walls. Some cracking at NW corner of gatehouse.
Indications of Movements of Structural Items on Slopes	None Observed
Trespassing on Slopes	No indications observed
Vegetation on Slopes	Moderate brush growth on d/s slope and at west side abutment.
Sloughing or Erosion of Slopes or Abutments	Sloughing observed at top of rip-rap on u/s slope and at groin areas.
Rock Slope Protection - Riprap Failures	Entire u/s face is paved per drawings. Minor displacement of rip-rap toward crest of dam on u/s face.

# VISUAL INSPECTION CHECK LIST

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)

National I.D. #: MA 00051

Date(s): December 4, 1980

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT (Con't)</u>	
Unusual Movement or Cracking at or near Toes	Sloughing observed at each groin area near the toe of the embankment.
Unusual Embankment or Downstream Seepage	Seepage at each groin area toward toe of dam and around sides of toe drains.
Piping or Boils	None Observed
Foundation Drainage Features	Toe Drains (see Appendix B)
Toe Drains	" " " " "
Instrumentation System	NA

VISUAL INSPECTION CHECK LIST

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)

National I.D. #: MA 00051

Date(s): December 4, 1980

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
a. Approach Channel (Approach Apron)	18'+ length - exposed during inspection.
General Condition	Very good.
Loose Rock Overhanging Channel	None observed.
Trees Overhanging Channel	None observed.
Floor of Approach Channel	Stone Masonry - very good condition.
b. Weir and Training Walls (Discharge Channel)	
General Condition of Concrete	Good.
Rust or Staining	None observed - Moss covered in some places.
Spalling	Minor spalling observed.
Any Visible Reinforcing	None observed.
Any Seepage or Efflorescence	None observed.
Drain Holes	None observed.
c. Discharge Channel	
General Condition	Good.

# VISUAL INSPECTION CHECK LIST

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)

National I.D. #: MA 00051

Date(s): December 4, 1980

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS (Con't)</u>	
Loose Rock Overhanging Channel	None observed.
Trees Overhanging Channel	Several, mostly coniferous, on east side of spillway channel.
Floor of Channel	Stone Masonry
Other Obstructions	None observed.

# VISUAL INSPECTION CHECK LIST

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)

National I.D. #: MA 00051

Date(s): December 4, 1980

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	NA
Slope Conditions	(Water enters gatehouse chamber
Bottom Conditions	via one of two 14-inch diameter
Rock Slides or Falls	intake pipes. See Appendix B.)
Log Boom	
Debris	
Condition of Concrete Lining	
Drains or Weep Holes	
b. Intake Structure (Gatehouse)	
Condition of Concrete	Exterior cracking observed at NW
Stop Logs and Slots	corner.
	NA

VISUAL INSPECTION CHECK LIST

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)  
 National I.D. #: MA 00051  
 Date(s): December 4, 1980

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	
General Condition	Good
Condition of Joints	NA
Spalling	Moderate at NW corner of gatehouse
Visible Reinforcing	None Observed
Rusting or Staining of Concrete	Minor Staining Observed
Any Seepage or Efflorescence	None Observed
Joint Alignment	Alignment appears to be good
Unusual Seepage or Leaks in Gate Chamber	Unknown
Cracks	Exterior cracking observed at NW corner of gatehouse
Rusting or Corrosion of Steel	None observed
b. Mechanical and Electrical	
Air Vents	No mechanical ventilation
Float Wells	None
Crane Hoist	NA

# VISUAL INSPECTION CHECK LIST

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)

National I.D. #: MA 00051

Date(s): December 4, 1980

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - CONTROL TOWER (Con't)</u>	
Elevator	None
Hydraulic System	NA
Service Gates	Three sluice gates - operable
Emergency Gates	Made operable after date of inspection
Lighting Protection System	Unknown
Emergency Power System	NA
Wiring and Lighting System in Gate Chamber	None

# VISUAL INSPECTION CHECK LIST

Project: Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)

National I.D. #: MA 00051

Date(s): December 4, 1980

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Concrete	No Headwall
Rust or Staining on Concrete	NA
Spalling	NA
Erosion or Cavitation	Erosion observed at outlet (see photos, Appendix C)
Cracking	NA
Alignment of Monoliths	NA
Alignment of Joints	NA
Numbering of Monoliths	NA




APPENDIX B  
CHECKLIST  
ENGINEERING DATA


APPENDIX E  
ENGINEERING DATA\*

TABLE OF CONTENTS

	<u>Page</u>
Cross Section of Proposed Louisiana Brook Reservoir Site (Sept. 25, 1933)	B-1
Plan of Proposed Reservoir on Louisiana Brook (October 2, 1933)	B-2
Sections through Dam and Gate House (October 2, 1933)	B-3
Plan and Sections of Wasteway (October 2, 1933)	B-4
1977 State Inspection Report	B-5 - B-8
1975 State Inspection Report	B-9 - B-17
1972 Correspondence to State from Owner	B-18 - B-19
1972 Correspondence to Owner from State	B-20

\*Drawings of the dam were obtained from the Northfield School,  
Director of Physical Plant. Miscellaneous information has been  
obtained from the Massachusetts DEQE files.






CROSS SECTION OF  
PROPOSED LOUISIANA WATER PROJECT

2

SCALE: 10 FT. TO 1 IN.

B-1



EAST NORTHFIELD SCHOOL

PLANT PROPOSED RESERVOIR


ON LOUISIANA BROOK

1965


Area 75: Acres  
Capacity 28 Mil. Gals.

1000 ft. 100 ft. 50 ft.  
1000 ft. 100 ft. 50 ft.







Section Through Dam  
Scale 1/4" = 10'




Section through Dam at Gate House  
Scale 1/4" = 10'




Plan of Dam at Gate House  
Scale 1/4" = 10'










EAST NORTHFIELD SCHOOLS  
 PLAN AND SECTIONS  
 OF WASTEWAY

SCALE, 4 IN. TO 1 FT.

OCT. 2, 1933

DESIGNED BY THE  
 CIVIL AND HYDRAULIC ENGINEERS  
 15 BRADON ST. CHICAGO, ILL.



Section A-A

# INSPECTION REPORT - DAMS AND RESERVOIRS

## 1. LOCATION:

City/Town Northfield County Franklin Dam No. 2-6-217-4

Name of Dam Northfield School Upper "Main" Reservoir Dam

Topo Sheet No. 134 Mass. Rect. Coordinates: N 627,900, E 351,900

Inspected by: Harold T. Shumway, On Sept. 23, 1977 Date 11/18/75 Last Inspection

## 2. OWNER/S: As of September 23, 1977

per: Assessors \_\_\_\_\_, Reg. of Deeds \_\_\_\_\_, Prev. Insp. X, Per. Contact X

1. Northfield, Mt. Hermon School, Northfield, Mass.  
Name St. & No. City/Town State Tel. No.

2. \_\_\_\_\_  
Name St. & No. City/Town State Tel. No.

3. \_\_\_\_\_  
Name St. & No. City/Town State Tel. No.

## 3. CARETAKER: (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Mr. Reynold Henry

Director of Physical Plant, Northfield School, East Northfield, Mass. 498-5311 ext. 244

Name St. & No. City/Town State Tel. No.

## 4.

### DATA:

No. of Pictures Taken None Sketches See description of Dam.  
Plans, Where Infiles of Physical Plant Office on School Grounds.

## 5.

### DEGREE OF HAZARD: (if dam should fail completely)\*

1. Minor \_\_\_\_\_ 3. Severe X

2. Moderate \_\_\_\_\_ 4. Disastrous \_\_\_\_\_

Comments: Approx. 25 million gallons impoundment-failure could affect streets and homes a short distance downstream.

\*This rating may change as land use changes (future development).

**6. OUTLETS: OUTLET CONTROLS AND DRAWDOWN**

South end of dam-concrete and stone masonry side chute

No. 1 Location and Type: overflow spillway-30' w x 4' h x 134'1Controls Yes, TYPE: 2'8" x 3" x 30' flashboardsAutomatic       . Manual X. Operative Yes X, No       .1" I.P. stanchions for flashboards designed to fail atComments: certain pressures.No. 2 Location and Type: Approx. center of dam-gate well intake structure.  
Intake pipes-2 ea. 14" dia. C.I. outlet pipes 1 ea.  
14" diam. C.I. water main-1 ea. 14" pipe blow-off.Controls Yes, Type: Gate valves on all pipesAutomatic       . Manual X. Operative Yes X, No       .Minor spalling of concrete on foundation walls of gatewell.Comments: 14" diam. blow-off pipe not shown on proposed plans of dam.No. 3 Location and Type:       Controls       , Type:       Automatic       . Manual       . Operative Yes       , No       .Comments:       Drawdown present Yes X, No       . Operative Yes X, No       .Comments: Operable per word of maintenance personnel.**7. DAM UPSTREAM FACE: Slope 2½:1, Depth Water at Dam 2'8" to top flashboards.**Material: Turf X. Brush & Trees       . Rock fill       . Masonry       . Wood       .Other 12" stone paving bedded in gravel.Condition: 1. Good X. 3. Major Repairs       .2. Minor Repairs       . 4. Urgent Repairs       .Comments:       **8. DAM DOWNSTREAM FACE: Slope 2:1.**

Conc. &amp; Stone

Material: Turf X. Brush & Trees       . Rock Fill       . Masonry X. Wood       .  
SpillwayOther       Condition: 1. Good       . 3. Major Repairs       .2. Minor Repairs       . 4. Urgent Repairs       .Comments: Slope has been cleared of brush & tree growth-growth still exists along  
toe of slope-seepage flows heavy-see remarks.

- 3 -

EMERGENCY SPILLWAY: Available Yes . Needed \_\_\_\_\_.

Height Above Normal Water: Unknown Ft. Flashboards in place 2'8" high at entrance to <sup>chute</sup>  
Width 30 Ft. Height 4 Ft. Material conc. walls-conc. & stone  
paved floor.

Condition: 1. Good \_\_\_\_\_ 3. Major Repairs \_\_\_\_\_  
2. Minor Repairs X 4. Urgent Repairs \_\_\_\_\_

Comments: Minor weed and grass growth noted in small crevices existing in  
stone paved floor.

10.

WATER LEVEL AT TIME OF INSPECTION: 5 Ft. Above \_\_\_\_\_ Below X \_\_\_\_\_.

Top Dam X F.L. Principal Spillway \_\_\_\_\_.

Other \_\_\_\_\_.

Normal Freeboard 1'-4" Ft. with flashboards in place.

11.

SUMMARY OF DEFICIENCIES NOTED:

Growth (Trees and Brush) on Embankment None found on slopes or top of embankment.

Animal Burrows and Washouts None found

Damage to Slopes or Top of Dam None found

Cracked or Damaged Masonry Minor spalling of concrete intake well.  
Seepage flow noted approx. 30' north and somewhat higher

Evidence of Seepage in elev. than outlet end of 6 inch V.C. pipe located at toe of slope.  
Questionable-see seepage above and leaks below.

Evidence of Piping A flow of several G.P.M. was emerging from outlet end of 6 inch V.C. pipe

Leaks at toe of slope-origin of pipe unknown-small flow also noted along side of pipe.  
see remarks.

Erosion None found

Trash and/or Debris Impeding Flow None found

Clogged or Blocked Spillway None found

Other \_\_\_\_\_.

## 9) OVERALL CONDITION:

1. Safe\_\_\_\_\_.
2. Minor repairs needed\_\_\_\_\_y\_\_\_\_\_.
3. Conditionally safe - major repairs needed\_\_\_\_\_.
4. Unsafe\_\_\_\_\_.
5. Reservoir impoundment no longer exists (explain)  
Recommend removal from inspection list\_\_\_\_\_.

13.

## REMARKS AND RECOMMENDATIONS: (Fully Explain)

Mr. C. E. Wiggin and Mr. Severance of the Northfield School physical plant were present during this inspection.


A considerable amount of brush and small trees have been cut on lower slope. The grade and alignment of dam appears good.

The seepage and or leak noted at toe of slope in area of 6 inch V.C. pipe is completely reversed from what was found 2 years ago, see inspection report dated 11-18-75. At present time a small seepage flow was noted emerging from the ground along the outside of the 6 inch V.C. pipe, while a flow of several G.P.M. was noted emerging from the 6 inch V.C. pipe itself. Origin of this 6 inch pipe is still unknown and so it is difficult to evaluate the seriousness of the existing conditions. A minor amount of fines were noted below the outlet end of the 6 inch pipe.

Another seepage area 30'  $\pm$  north of the 6 inch V.C. pipe and higher up on the slope was also noted. This area existed at last inspection and does not appear to have increased any in volume of flow. According to proposed plans on file of dam dated October 2, 1933, a concrete core wall exists to within 2 ft. of top of dam. The six inch V.C. pipe is not shown on these plans, nor is a 14 inch C.I. blow-off pipe which outlets just south of the six inch pipe.

It is assumed that the 14 inch blow-off pipe originates in the gatehouse well. Since the well has never been drained, to the memory or knowledge of present school maintenance personnel, it could be that the 6 inch V.C. pipe also originates in the gate well and that the seepage flows or leaks start in that area. It would seem advisable for the owners to check before it creates a serious hazard to safety of dam.

The dam appeared to still be basically sound and safe on day of inspection.



# *The Commonwealth of Massachusetts*

EXECUTIVE OFFICE OF ENVIRONMENTAL AFFAIRS  
DEPARTMENT OF ENVIRONMENTAL QUALITY ENGR.  
DIVISION OF WATERWAYS

*100 Nashua Street, Boston 02114*

June 11, 1976

Mr. Reynold Henry  
Northfield School  
East Northfield, Massachusetts

RE: Inspection Dam #2-~~26~~-217-4  
Northfield  
Northfield School Upper Main  
Reservoir Dam

Dear Sir:

On November 18, 1975, an Engineer from the Massachusetts Department of Public Works made a visual inspection of the above dam. Our records indicate the owner to be Mt. Hermon School, Northfield. If this information is incorrect will you please notify this office.

The inspection was made in accordance with the provisions of Chapter 253 of the Massachusetts General Laws as amended (Dams-Safety Act). Chapter 706 of the Acts of 1975 transferred the jurisdiction of the so-called "Dams Safety Program" to the Commissioner of the Department of Environmental Quality Engineering.

The results of the inspection indicate that this dam is safe; however the following conditions were noted that require attention:

Remove brush from top and downstream slope.

On northerly end of dike, at toe of slope, a 6" V.C. pipe end was observed. There appears to be considerable flow along the outside of this pipe.

It is recommended that conditions in this area be closely monitored for any changes in characteristics.

We call these conditions to your attention before they become serious and more expensive to correct. With any correspondence please include the number of the Dam as indicated above.

Very truly yours,

*David Standley*  
DAVID STANDLEY  
COMMISSIONER

A.Mc:eh

B-9

# INSPECTION REPORT - DAMS AND RESERVOIRS

## 1. LOCATION:

~~City~~/Town Northfield . County Franklin . Dam No. 2-6-217-4 .

Name of Dam Northfield School Upper "Main" Reservoir Dam .

Mass. Rect.

Topo Sheet No. 13 A . Coordinates: N 627,900 , E 351,900 .

Date

Inspected by: Harold T. Shumway , On Nov. 18, 1975 . Last Inspection 9-5-73 .

## 2. OWNER/S: As of November 18, 1975

per: Assessors \_\_\_\_\_, Reg. of Deeds \_\_\_\_\_, Inv. Insp. X , Per. Contact X .

1. Northfield, Mt. Hermon School, Northfield, Mass.

Name	St. & No.	City/Town	State	Tel. No.

Name	St. & No.	City/Town	State	Tel. No.

Name	St. & No.	City/Town	State	Tel. No.

## 3. CAPTAIN: (if any) e.g. superintendent, plant manager, appointed by absentee owner, appointed by multi owners.

Mr. Reynold Henry Northfield School,

Director of Physical Plant East Northfield, Mass. 413 - 498-5311 Ext. 244

Name	St. & No.	City/Town	State	Tel. No.

## 4. DATA:

No. of Pictures Taken none . Sketches See description of Dam.  
Plans, Where Files of physical plant office on school grounds. .

## 5. DEGREE OF HAZARD: (if dam should fail completely)\*

1. Minor \_\_\_\_\_ . 3. Severe X \_\_\_\_\_ .

2. Moderate \_\_\_\_\_ . 4. Disastrous \_\_\_\_\_ .

Comments: 31 million gallons impoundment - could affect streets and homes down-  
stream a short distance.

\*This rating may change as land use changes (future development).



6. OUTLETS: OUTLET CONTROLS AND DRAWDOWN

No. 1 Location and Type: conc. and stone masonry side chute  
South end of dam - spillway - 30'W. x 4'H. x 134'L.

Controls yes, TYPE: 3" x 2'-8" x 30' flashboards.

Automatic       . Manual X. Operative Yes X, No       .

Comments: 1" dia. I.P. stanchions for flashboards designed to fail at certain pressures.

No. 2 Location and Type: Intake - 2 ea. 14" dia. C.I. pipes - outlet pipes - 1 ea. 14" dia  
C.I. water main - 1 ea. 14" pipe blow-off, all pipes equipped

Controls yes, Type: with gate valves.

Automatic       . Manual X. Operative Yes X, No       .

Comments: 14" dia. C.I. blow-off pipe not shown on proposed plans of dam.

No. 3 Location and Type:       

Controls       , Type:       

Automatic       . Manual       . Operative Yes       , No       .

Comments:       

Drawdown present Yes X, No       . Operative Yes X, No       .

Comments: Per word of Maintenance Supervisor.

7. DAM UPSTREAM FACE: Slope 2 1/2:1, Depth Water at Dam 2'-8" to top flashboards.

Material: Turf X. Brush & Trees       . Rock fill       . Masonry       . Wood       .

Other 12" stone paving bedded in gravel.

Condition: 1. Good X. 3. Major Repairs       .

2. Minor Repairs       . 4. Urgent Repairs       .

Comments: Heavy growth of weeds, should be cut off to prevent brush growth.

8. DAM DOWNSTREAM FACE: Slope 2:1.

Material: Turf X. Brush & Trees X. Rock Fill       . Conc. & stone  
 Masonry X. Wood       .  
 Spillway

Other       

Condition: 1. Good       . 3. Major Repairs X.

2. Minor Repairs       . 4. Urgent Repairs       .

Comments: Heavy flow of water along outside of a 6" dia. V.C. pipe at toe of  
slope - origin unknown - see remarks.

- 3 -

9. EMERGENCY SPILLWAY: Available yes. Needed \_\_\_\_\_.

Height Above Normal Water: unknown Ft. - Flashboards 2'-8" H. at entrance.

Width 30 Ft. Height 4 Ft. Material conc. walls - conc. & stone  
paved floor.

Condition: 1. Good \_\_\_\_\_ 3. Major Repairs \_\_\_\_\_

2. Minor Repairs X 4. Urgent Repairs \_\_\_\_\_

Comments: Some weed and grass growth in small crevices in stone paved floor  
of spillway.

10. WATER LEVEL AT TIME OF INSPECTION: 1 1/3 Ft. Above \_\_\_\_\_ Below X \_\_\_\_\_

Top Dam X F.L. Principal Spillway \_\_\_\_\_

Other \_\_\_\_\_

Normal Freeboard 1'-4" Ft. with flashboards in place.

11. SUMMARY OF DEFICIENCIES NOTED:

Growth (Trees and Brush) on Embankment yes - lower part of downstream slope heavily wooded.

Animal Burrows and Washouts None found

Damage to Slopes or Top of Dam See erosion below.

Cracked or Damaged Masonry yes - some grouting missing in paved floor of spillway - minor cracks in conc. side walls.

Evidence of Seepage yes - on southerly end of toe of slope and on northerly end.

Evidence of Piping Questionable - see remarks.

Leaks yes - see item #8 and remarks.

Erosion yes - minor erosion on northerly end of dike on downstream slope.

Trash and/or Debris Impeding Flow None found

Clogged or Blocked Spillway 2'-8" height of flashboards in place.

Other \_\_\_\_\_

- 4 -

(12.)

## OVERALL CONDITION:

1. Safe\_\_\_\_\_.
2. Minor repairs needed x\_\_\_\_\_.
3. Conditionally safe - major repairs needed\_\_\_\_\_.
4. Unsafe\_\_\_\_\_.
5. Reservoir impoundment no longer exists (explain)  
Recommend removal from inspection list\_\_\_\_\_.

(13.)

## REMARKS AND RECOMMENDATIONS: (Fully Explain)

Alignment and grade of this embankment type dam appear good. Upstream slope appears stable. A year's growth of weeds and wild grasses was noted on top and downstream slope. Lower elevations of downstream slope is heavily wooded with fir trees and brush. At approx. tree line on southerly end of embankment some seepage was noted. There was also minor seepage noted on northerly end of dike at toe of first slope.

Flashboards were in place on side chute spillway intake to a height of 2'-8". Water was overflowing these flashboards 1"  $\pm$  in depth at time of inspection. Some minor spalling of grouting in spillway floor downstream of flashboards was noted and a minor weed growth was noted in crevices.

On the northerly end of dike at toe of slope near outlet end of 14" C.I. blow-off pipe a 6 inc V.C. pipe end was observed. A small flow of water was emerging from this pipe but a much larger flow of red oxide stained water was flowing along northerly side and outside of this 6 inc pipe. Origin and purpose of this pipe was unknown by Mr. Reynold Henry, Physical Plant Director, and two other maintenance employees who were present during this inspection. One of the employees, who has apparently worked for the school for many years, stated that there had been a flow of water in this area for years. He also stated that flow seemed to be greater in volume than usual.

This flow of water, coupled with a very wet, soft ground, seepage area on the slope direct above and approx. 10' to 15' higher up the slope would appear to indicate a large leak or possible a piping condition. There did not appear to be any accumulation of fines in outlet area of this water flow but invert of six inch V.C. pipe was 1/3 full of silt.


This condition was discussed with Mr. Henry who stated he would keep a close check on this flow for any further enlargement in volume.

The District is rating this dam as safe, minor repairs needed, but recommends that owner be advised to establish origin of 6 inch V.C. pipe if possible and to closely monitor the flow of water along outside of this pipe for any changes. Enclosed sketches show approx. location of seepage areas and 6" V.C. pipe.

# Pond Area

H.T.S.  
11-5-75

Sheet 1 of 4 sheets  
Northfield School Upper 'Main'  
Reservoir  
Town of Northfield, Mass  
Nov. 18, 1975




Sketch - Nov  
To scale

Plan of proposed reservoir  
on Northfield Pond  
Nov. 18, 1975

Oct. 20, 1975

Notes in red as found  
on Nov. 18, 1975 - H.T.S.

Section Through Dam



NOTE  
copied from plans  
in file at school  
entrance office

5

DAM + Gate House =




55



Dear Mr. Campbell:

It would not be practical to remove the flashboards from our Reservoir spillway during an essential part of the Reservoir operating season. To remove the flashboards, we would have to reduce the operating capacity of our Reservoir. Our spillway supports are so designed that they will operate satisfactorily during the off period. Our spillway is designed to operate with the flashboards, of course, but it can be operated without them. I have always operated with the flashboards, but I can ask you to reconsider your recommendation. I can have the facility, however, and I can operate without the flashboards.




December 4, 1972

Mr. Bruce Campbell  
Commissioner

valve, which would increase the outflow from our main Reservoir and consequently cause the dam to overflow in a small intake Reservoir below the main Reservoir. This should be able to relieve pressure as water tables continue to rise. I can understand and appreciate your concern in this regard, however, if we are to operate our Reservoir properly, I feel compelled to give you the above information.

Sir, will you please reply to this communication?

Sincerely,



Carl A. Pelzel  
Director of Physical  
Plant

CP/g



December 12, 1972

Mr. Carl A. Pelzel  
Director of Physical Plant  
Northfield School  
East Northfield, Massachusetts

RE: Dam #2-6-217-4  
Northfield  
Northfield Schools Upper  
Reservoir Dam

Dear Mr. Pelzel:

Your letter dated December 4, 1972, to Commissioner Campbell, has been referred to the Division of Waterways.

The Commissioners "Notice to Owners or Caretakers of Dams" is intended only as an alert to responsible parties. The design of the flashboards, as described in your letter apparently has the "built-in" safety factor of failure when predetermined stresses exist. Other safety features such as valves, trash racks, etc. apparently have been checked and found operable, thus satisfying the intent of the notice.

If this office may be of further assistance, please do not hesitate to contact us.

Very truly yours,

*Fred C. Schwelm*  
FRED. C. SCHWELM, P.E.  
Deputy Chief Engineer


*LJB*  
LRA:hlb  
cc:F.J.Hoey  
R. Salls

APPENDIX C  
PHOTOGRAPHS

APPENDIX C  
SELECTED PHOTOGRAPHS OF PROJECT

	<u>Page No.</u>
Site Plan	A
<u>PHOTOGRAPHS</u>	
<u>No.</u>	
1. View along centerline of dam from the south abutment. (12/4/80)	1
2. Downstream face of dam showing tree and brush cover. (12/4/80)	1
3. Gatehouse on crest of dam. (12/4/80)	2
4. Spillway inlet channel and spillway. (12/4/80)	2
5. Spillway outlet channel and spillway looking upstream. (12/4/80)	3
6. Seepage at downstream toe of the dam. (12/4/80)	3
7. Seepage at downstream toe of the dam. (12/4/80)	4
8. 6-inch pipe downstream of the spillway outlet channel. (12/4/80)	4
9. Holding pond about 700 feet downstream from the dam. (12/4/80)	5
10. Potential damage area approximately 3,000 feet down- stream from the dam. (12/4/80)	5

Northfield School Upper Reservoir Dam A \$ 1/27/61 2060-002






1. VIEW ALONG CENTERLINE OF DAM FROM THE SOUTH ABUTMENT. (12/4/50)



2. DOWNSTREAM FACE OF DAM SHOWING TREE AND BRUSH COVER. (12/4/50)



3. GATEHOUSE ON CREST OF DAM. (2487)



4. SPILLWAY INLET CHANNEL AND SPILLWAY. (2488)



5. SPILLWAY OUTLET CHANNEL AND SPILLWAY LOOKING UPSTREAM.

(12/4/80)



6. SEEPAGE AT DOWNSTREAM TOE OF THE DAM. (12/4/80)



7. SEEPAGE AT DOWNSTREAM TOE OF THE DAM. (12/4/80)



8. 4-INCH PIPE DOWNSTREAM OF THE SPILLWAY OUTLET CHANNEL.  
(12/4/80)





9. HOLDING POND ABOUT 700 FEET DOWNSTREAM FROM THE DAM. (12/4/80)



10. POTENTIAL PASSAGE AREA APPROXIMATELY 3000 FEET (12/4/80)  
DOWNSTREAM FROM THE DAM.


APPENDIX D  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

## APPENDIX D

### HYDROLOGIC AND HYDRAULIC COMPUTATIONS

#### TABLE OF CONTENTS

	<u>Page</u>
Regional Vicinity Map, Figure 1, showing Downstream Hazard Area	D-1
Tp Calculation	D-2
Sketch: Dam Elevation and Spillway Dimensions	D-2
Stage - Discharge Table	D-3
Stage - Storage Table	D-4
PMP Data	D-4
Stage - Discharge and Stage - Storage Graphs	D-5
Downstream Routing Information:	
Section: Upper Reach of Louisiana Brook	D-6
Section @ Winchester Road	D-6
Stage - Discharge Table (Winchester Road)	D-7
Channel Section @ D/S Hazard Area	D-8
Stage - Storage Table (Winchester Road)	D-8
HEC-1 Dam Safety Version, Computer Output	D-9 to D-12
HEC-1DB Dam Safety Version, Breach Analysis, Computer Output (1½ Hour Breach)	D-13 to D-19
Summary of 15-Minute Breach, Computer Output (Used for this Report)	D-20, D-21





O'BRIEN & GERE

SUBJECT	SHEET	BY	DATE	JOB NO.
Grandin Reservoir Dam	D-2	ADH	1/09/81	2060.002

North Field School Upper Reservoir Dam

1 &

2/25/81

(I.) Drainage Area : 0.6 sq. mi.

(II.) Snyder Hydrograph Coefficients

$$C_T = 2.0 \quad \& \quad C_P = 0.6$$

(III.)  $T_p$  Calculation


$$T_p = C_T (L \times L_{ca})^{0.3}$$

- where  $L$  = main channel length from the outflow point to the upstream watershed boundary (river miles)

and  $L_{ca}$  = main channel length from the outflow point to a point opposite the center of the river basin (river miles)

$$T_p = (2.0) (1.5 \times 0.85)^{0.3} = 2.15 \Rightarrow \text{say } \underline{2.25 \text{ Hours}}$$

(IV.) Sketch : Dam Elevation & Spillway Dimensions





OBRIEN &amp; GERE

SUBJECT

Grandin Reservoir Dam

SHEET

D-3

BY

ADH

DATE

1/14/81

JOB NO.

2060.002

(Northfield School Upper Reservoir Dam)

12 4/8/81

## (V.) Stage - Discharge Table \*

Elevation (NGVD)	H <sub>1</sub> (ft)	Q <sub>1</sub> (cfs)	H <sub>2</sub> (ft)	Q <sub>2</sub> (cfs)	H <sub>3</sub> (ft)	Q <sub>3</sub> (cfs)	Σ Q (cfs)
686	0	0	—	—	35.5	20	20
687	1.0	99	—	—	36.5	21	120
687.5	1.5	182	0	0	37	21	203
688	2.0	280	0.5	234	37.5	21	535
689	3.0	514	1.5	1,247	38.5	21	1,782
690	4.0	792	2.5	2,744	39.5	22	3,558

Where  $Q_1$  = Discharge over spillway
$$(Q = CLH^{3/2}; C = 3.3 \text{ for } 30' \text{ wide sharp-crested weir; free discharge over weir.})$$
 $Q_2$  = Flow over dam crest
$$(Q = CLH^{3/2}; C = 2.6 \text{ for broad-crested weir; side slopes } 5H:1V \text{ \& } 7H:1V)$$
 $Q_3$  = Discharge through 14-inch drain
$$(Q = 1.318 C_{hw} A P^{0.63 \cdot 0.54} \text{ (Hazen-Williams)};$$

$C_{hw}$  assumed to be 95; head loss computed with effective length of 271 feet)

\* The stage-discharge relationship was developed assuming that the flashboards will remain in place for the duration of the overtopping period.



O'BRIEN &amp; GERE

SUBJECT	SHEET	BY	DATE	JOB NO.
Grandin Reservoir Dam	D-4	ADH	1/15/81	2060.002

(Northfield School Upper Reservoir Dam)

13

4/25/81

(VI.) Stage - Storage Table \*

Description	Elevation (MSVD)	Area (acres)	Storage (acre-feet)
Toe of Dam	656.5±	0	0
Spillway Crest	686±	7.5	91
Top of Dam	687.5±	8.8	104
Test Flood El.	688.0±	9.4	109

\* Areas have been estimated from the "Northfield, Mass. - NH - VT." USGS map. Storage data have been computed according to the conical method by the HEC-1-DB computer program.

(VII.) PMP Data (Drainage Area  $\approx 0.6 \text{ mi}^2$ )

24-Hr.  $200 \text{ mi}^2$  probable maximum precipitation:  
 $\approx \underline{20.2 \text{ inches}}$  (Ref.: HMS #33)

Also,


6-Hr.	% of index for this basin	$\approx$	<u>111</u>
12-Hr.	" " " " " "	$\approx$	<u>123</u>
24-Hr.	" " " " " "		<u>132</u>

Substation	SHEET	BY	DATE	JOB NO.
Grandin Reservoir Dam	D-5	ADH	1/12/81	2060.002

(Northfield School Upper Reservoir Dam)

2/25/81

STORAGE - AC. FT.



DISCHARGE - CFS

ELEVATION - Ft. (NGVD)





O'BRIEN & GERE

SUBJECT	SHEET	BY	DATE	JOB NO.
Grandin Reservoir Dam	D-6	ADH	1/15/81	2060.002


(North School Upper Reservoir Dam)

14


2/25/81

### (VIII.) Downstream Routing Information

The break analysis for Grandin Reservoir Dam included routing the flow along Louisiana Brook for a distance of approximately 0.6 mile to the hazard area. A stage-discharge relationship was determined for routing flow through a 4' x 4' box culvert and over Winchester Road at the hazard area. The following cross sections were used in the routing procedure:



### Section: Upper Reach of Louisiana Brook (Not To Scale)



### Section @ Winchester Road (Not To Scale)



O'BRIEN &amp; GERE

SUBJECT	SHEET	BY	DATE	JOB NO.
Grandin Reservoir Dam (Northfield School Upper Reservoir Dam)	D-7	ADH	1/15/81	2060.00.2

### (VIII.) Downstream Routing Information (cont.)

The following stage-discharge table was compiled, based upon the section at Winchester Road illustrated on p. D-6 of this Appendix. Flow through the culvert was calculated through the use of the orifice equation\* ( $Q = C_a \sqrt{gh}$ ), where  $C = 0.79$ . Flow over the road was calculated through the use of the weir flow equation ( $Q = CLH^{3/2}$ ), where  $C = 2.7$  for the paved broad-crested weir.

#### Stage-Discharge Table: (Section @ Winchester Road.)

Elevation (NGVD)	$H_1$ (ft)	$Q_1$ (cfs)	$H_2$ (ft)	$Q_2$ (cfs)	$\Sigma Q$ (cfs)
381	0	0	—	—	0
382	1	22	—	—	22
383	2	58	—	—	58
384	3	99	—	—	99
385	4	117	—	—	117
386	5	143	—	—	143
387	6	176	—	—	176
389	8	227	1	162	389
390	9	249	2	918	1,167
391	10	268	3	3,090	3,358
392	11	336	4	9,029	9,365

\* Note that Manning's Equation was used for open channel flow. ( $n = .025$ ,  $s = .025$ )



\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (FILE-1)  
 FOR SAFETY DIVISION JULY 1978  
 LAST MODIFICATION 01 APR 80  
 \*\*\*\*\*

HYDROLOGIC DATA FILE OF GRANDIN RESERVOIR DAM									
NATURAL FLOOD PROTECTION PROGRAM									
GRAND DIVISION CURVES OF FREQUENCIES									
1	01	0	15	0	0	0	0	0	0
2	02	0	15	0	0	0	0	0	0
3	03	0	15	0	0	0	0	0	0
4	04	0	15	0	0	0	0	0	0
5	05	0	15	0	0	0	0	0	0
6	06	0	15	0	0	0	0	0	0
7	07	0	15	0	0	0	0	0	0
8	08	0	15	0	0	0	0	0	0
9	09	0	15	0	0	0	0	0	0
10	10	0	15	0	0	0	0	0	0
11	11	0	15	0	0	0	0	0	0
12	12	0	15	0	0	0	0	0	0
13	13	0	15	0	0	0	0	0	0
14	14	0	15	0	0	0	0	0	0
15	15	0	15	0	0	0	0	0	0
16	16	0	15	0	0	0	0	0	0
17	17	0	15	0	0	0	0	0	0
18	18	0	15	0	0	0	0	0	0
19	19	0	15	0	0	0	0	0	0
20	20	0	15	0	0	0	0	0	0
21	21	0	15	0	0	0	0	0	0
22	22	0	15	0	0	0	0	0	0
23	23	0	15	0	0	0	0	0	0
24	24	0	15	0	0	0	0	0	0
25	25	0	15	0	0	0	0	0	0
26	26	0	15	0	0	0	0	0	0
27	27	0	15	0	0	0	0	0	0
28	28	0	15	0	0	0	0	0	0
29	29	0	15	0	0	0	0	0	0
30	30	0	15	0	0	0	0	0	0
31	31	0	15	0	0	0	0	0	0
32	32	0	15	0	0	0	0	0	0
33	33	0	15	0	0	0	0	0	0
34	34	0	15	0	0	0	0	0	0
35	35	0	15	0	0	0	0	0	0
36	36	0	15	0	0	0	0	0	0
37	37	0	15	0	0	0	0	0	0
38	38	0	15	0	0	0	0	0	0
39	39	0	15	0	0	0	0	0	0
40	40	0	15	0	0	0	0	0	0
41	41	0	15	0	0	0	0	0	0
42	42	0	15	0	0	0	0	0	0
43	43	0	15	0	0	0	0	0	0
44	44	0	15	0	0	0	0	0	0
45	45	0	15	0	0	0	0	0	0
46	46	0	15	0	0	0	0	0	0
47	47	0	15	0	0	0	0	0	0
48	48	0	15	0	0	0	0	0	0
49	49	0	15	0	0	0	0	0	0
50	50	0	15	0	0	0	0	0	0
51	51	0	15	0	0	0	0	0	0
52	52	0	15	0	0	0	0	0	0
53	53	0	15	0	0	0	0	0	0
54	54	0	15	0	0	0	0	0	0
55	55	0	15	0	0	0	0	0	0
56	56	0	15	0	0	0	0	0	0
57	57	0	15	0	0	0	0	0	0
58	58	0	15	0	0	0	0	0	0
59	59	0	15	0	0	0	0	0	0
60	60	0	15	0	0	0	0	0	0
61	61	0	15	0	0	0	0	0	0
62	62	0	15	0	0	0	0	0	0
63	63	0	15	0	0	0	0	0	0
64	64	0	15	0	0	0	0	0	0
65	65	0	15	0	0	0	0	0	0
66	66	0	15	0	0	0	0	0	0
67	67	0	15	0	0	0	0	0	0
68	68	0	15	0	0	0	0	0	0
69	69	0	15	0	0	0	0	0	0
70	70	0	15	0	0	0	0	0	0
71	71	0	15	0	0	0	0	0	0
72	72	0	15	0	0	0	0	0	0
73	73	0	15	0	0	0	0	0	0
74	74	0	15	0	0	0	0	0	0
75	75	0	15	0	0	0	0	0	0
76	76	0	15	0	0	0	0	0	0
77	77	0	15	0	0	0	0	0	0
78	78	0	15	0	0	0	0	0	0
79	79	0	15	0	0	0	0	0	0
80	80	0	15	0	0	0	0	0	0
81	81	0	15	0	0	0	0	0	0
82	82	0	15	0	0	0	0	0	0
83	83	0	15	0	0	0	0	0	0
84	84	0	15	0	0	0	0	0	0
85	85	0	15	0	0	0	0	0	0
86	86	0	15	0	0	0	0	0	0
87	87	0	15	0	0	0	0	0	0
88	88	0	15	0	0	0	0	0	0
89	89	0	15	0	0	0	0	0	0
90	90	0	15	0	0	0	0	0	0
91	91	0	15	0	0	0	0	0	0
92	92	0	15	0	0	0	0	0	0
93	93	0	15	0	0	0	0	0	0
94	94	0	15	0	0	0	0	0	0
95	95	0	15	0	0	0	0	0	0
96	96	0	15	0	0	0	0	0	0
97	97	0	15	0	0	0	0	0	0
98	98	0	15	0	0	0	0	0	0
99	99	0	15	0	0	0	0	0	0
100	100	0	15	0	0	0	0	0	0

ROUTE HYDROGRAPH AT  
 ROUTE HYDROGRAPH TO  
 END OF TUNNEL

PERIOD OF SEVERITY OF EXCESSIVE FLOOD CONDITIONS

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (FILE-1)  
 FOR SAFETY DIVISION JULY 1978  
 LAST MODIFICATION 01 APR 80  
 \*\*\*\*\*

RUN DATE 01/01/22  
 TIME 01.40.51

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (FILE-1)  
 FOR SAFETY DIVISION JULY 1978  
 LAST MODIFICATION 01 APR 80  
 \*\*\*\*\*

HYDROLOGIC DATA FILE OF GRANDIN RESERVOIR DAM									
NATURAL FLOOD PROTECTION PROGRAM									
GRAND DIVISION CURVES OF FREQUENCIES									
1	01	0	15	0	0	0	0	0	0
2	02	0	15	0	0	0	0	0	0
3	03	0	15	0	0	0	0	0	0
4	04	0	15	0	0	0	0	0	0
5	05	0	15	0	0	0	0	0	0
6	06	0	15	0	0	0	0	0	0
7	07	0	15	0	0	0	0	0	0
8	08	0	15	0	0	0	0	0	0
9	09	0	15	0	0	0	0	0	0
10	10	0	15	0	0	0	0	0	0
11	11	0	15	0	0	0	0	0	0
12	12	0	15	0	0	0	0	0	0
13	13	0	15	0	0	0	0	0	0
14	14	0	15	0	0	0	0	0	0
15	15	0	15	0	0	0	0	0	0
16	16	0	15	0	0	0	0	0	0
17	17	0	15	0	0	0	0	0	0
18	18	0	15	0	0	0	0	0	0
19	19	0	15	0	0	0	0	0	0
20	20	0	15	0	0	0	0	0	0
21	21	0	15	0	0	0	0	0	0
22	22	0	15	0	0	0	0	0	0
23	23	0	15	0	0	0	0	0	0
24	24	0	15	0	0	0	0	0	0
25	25	0	15	0	0	0	0	0	0
26	26	0	15	0	0	0	0	0	0
27	27	0	15	0	0	0	0	0	0
28	28	0	15	0	0	0	0	0	0
29	29	0	15	0	0	0	0	0	0
30	30	0	15	0	0	0	0	0	0
31	31	0	15	0	0	0	0	0	0
32	32	0	15	0	0	0	0	0	0
33	33	0	15	0	0	0	0	0	0
34	34	0	15	0	0	0	0	0	0
35	35	0	15	0	0	0	0	0	0
36	36	0	15	0	0	0	0	0	0
37	37	0	15	0	0	0	0	0	0
38	38	0	15	0	0	0	0	0	0
39	39	0	15	0	0	0	0	0	0
40	40	0	15	0	0	0	0	0	0
41	41	0	15	0	0	0	0	0	0
42	42	0	15	0	0	0	0	0	0
43	43	0	15	0	0	0	0	0	0
44	44	0	15	0	0	0	0	0	0
45	45	0	15	0	0	0	0	0	0
46	46	0	15	0	0	0	0	0	0
47									

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

# SUB AREA RIBBON COMPUTATION

## FLOW TO GRADE RIBBON

INLET	FLOW	INLET	INLET	INLET	INLET	INLET	INLET	INLET	INLET
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

## HYDROGRAPH DATA

INLET	FLOW	INLET	INLET	INLET	INLET	INLET	INLET	INLET	INLET
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

## PRECIP DATA

INLET	FLOW	INLET	INLET	INLET	INLET	INLET	INLET	INLET	INLET
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

## UNIT HYDROGRAPH DATA

INLET	FLOW	INLET	INLET	INLET	INLET	INLET	INLET	INLET	INLET
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

## UNIT HYDROGRAPH DATA

INLET	FLOW	INLET	INLET	INLET	INLET	INLET	INLET	INLET	INLET
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

## UNIT HYDROGRAPH DATA

INLET	FLOW	INLET	INLET	INLET	INLET	INLET	INLET	INLET	INLET
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

## UNIT HYDROGRAPH DATA

INLET	FLOW	INLET	INLET	INLET	INLET	INLET	INLET	INLET	INLET
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

# HYDROGRAPH ROUTING

## ROUTED OUTFLOW FROM GRANITE RESERVOIR

ISAR	ICOMP	IFCON	IFAGE	IFPT	IFRT	IFAGE	IFOUT
GR001	1	0	0	0	0	1	0

ROUTING DATA

LOSS	AVG	LOSS	LOSS	LOSS	LOSS	LOSS	LOSS
0.0	0.00	0.00	1	1	0	0	0

NSITS	NSIDL	LAG	ANSKR	X	TSK	STORA	ISFAT
1	0	0	0.000	0.000	0.000	-606.	1
STAGE	686.00	487.00	687.50	688.00	689.00	690.00	
FLOW	0.00	120.00	203.00	535.00	1702.00	3558.00	

SURFACE AREA= 0. 8. 11.  
CAPACITY= 0. 91. 177.  
ELEVATION= 653. 606. 695.

PREL	SPWID	CHOW	EXFW	ELEV	COOL	CAREA	EXFL
686.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

PAM DATA

TOTLL	CURR	EXFL	DAMWID
687.5	0.0	0.0	0.

PEAK OUTFLOW IS 49. AT TIME 18.75 HOURS

PEAK OUTFLOW IS 99. AT TIME 18.75 HOURS

PEAK OUTFLOW IS 152. AT TIME 18.50 HOURS

PEAK OUTFLOW IS 206. AT TIME 18.50 HOURS

PEAK OUTFLOW IS 272. AT TIME 18.00 HOURS

PEAK OUTFLOW IS 540. AT TIME 18.00 HOURS

PEAK OUTFLOW IS 820. AT TIME 18.00 HOURS

PEAK OUTFLOW IS 1024. AT TIME 18.00 HOURS

\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*  
\*\*\*\*\*

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN RATIO	1	2	3	4	5	6	7	8
				.05	.10	.15	.20	.25	.50	.75	1.00
RATIOS APPLIED TO FLOWS											
HYDROGRAPH AT	INGRD	.60	1	55.	109.	164.	219.	273.	536.	800.	1097.
	(	1.55)	(	1.55)	3.09)	4.64)	6.19)	7.74)	15.47)	23.21)	30.83)
ROUTED TO	GRDOUT	.60	1	49.	99.	152.	206.	272.	539.	800.	1097.
	(	1.55)	(	1.40)	2.79)	4.30)	5.84)	7.26)	15.41)	23.21)	30.83)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION	INITIAL VALUE	SETBACK CREST	TIME OF DAM
	STORAGE	686.00	686.00	687.50
	OUTFLOW	91.	91.	104.
		0.	0.	203.

RATIO OF FRR	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM INLET OVER DAM	MAXIMUM STORAGE ACFT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FLOODING HOURS
.05	686.41	0.00	95.	49.	0.00	18.25	0.00
.10	686.82	0.00	98.	99.	0.00	18.25	0.00
.15	687.19	0.00	101.	152.	0.00	18.50	0.00
.20	687.50	.00	104.	206.	.25	18.50	0.00
.25	687.60	.10	105.	272.	2.25	18.00	0.00
.50	688.01	.51	108.	548.	5.00	18.00	0.00
.75	688.23	.73	110.	820.	6.75	18.00	0.00
1.00	688.45	.95	112.	1094.	0.00	18.00	0.00





RUN DATE\* 81/02/24.  
TIME\* 06.03.40.

HYDROLOGIC ANALYSIS OF GRANDIN RESERVOIR DAM BREACH  
NATIONAL DAM INSPECTION PROGRAM  
NEW ENGLAND DIVISION - CORPS OF ENGINEERS

JOB SPECIFICATION									
NO	NRK	NMIN	IDAY	JHR	JMIN	METRE	IFLT	IFRT	NSIAR
200	0	10	0	0	0	0	0	-4	0
			JOFER	NMI	LEOFI	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSIS TO BE PERFORMED  
PLAN=2 METHOD=1 LRTO=1

REF ID: A7105=
































































































































































## SUB-AREA RUNOFF COMPUTATION

INFLOW TO GRANDIN RESERVOIR DAM

ISTAD	ICOMP	IECON	ITIME	JFL1	JFRT	INAME	ISTAGE	IAUTH
UNGER	0	0	0	0	0	1	0	0

## HYDROGRAPH DATA

IHYNG	IJUNG	JAREA	SNAP	IRSDA	IRSFC	RATIO	ISNOW	ISSME	LOCAL
1	1	.60	0.00	.60	0.00	0.000	0	1	9

REF ID: A7434

	FMS	R6	R12	R24	R48	R72	R96
SFFE							
0.00	20.20	111.00	123.00	132.00	0.00	0.00	0.00

TRSEC COMPUTED BY THE PROGRAM IS 1.000

LOSS DATA

LEOGL	STERR	PLINE	STIOL	EPAIN	STERS	RIDON	STELL	CNSIL	ALSMY	ELIIM
0	0.00	0.00	1.00	0.00	0.00	1.00	0.00	.05	0.00	0.00

## UNIT HYDROGRAPH 101A

[illegible]

REF: 1010

	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283	2284	2285	2286	2287	2288	2289	2290	2291	2292	2293	2294	2295	2296	2297	2298	2299	2300	2301	2302	2303	2304	2305	2306	2307	2308	2309	2310	2311	2312	2313	2314	2315	2316	2317	2318	2319	2320	2321	2322	2323	2324	2325	2326	2327	2328	2329	2330	2331	2332	2333	2334	2335	2336	2337	2338	2339	2340	2341	2342	2343	2344	2345	2346	2347	2348	2349	2350	2351	2352	2353	2354	2355	2356	2357	2358	2359	2360	2361	2362	2363	2364	2365	2366	2367	2368	2369	2370	2371	2372	2373	2374	2375	2376	2377	2378	2379	2380	2381	2382	2383	2384	2385	2386	2387	2388	2389	2390	2391	2392	2393	2394	2395	2396	2397	2398	2399	2400	2401	2402	2403	2404	2405	2406	2407	2408	2409	2410	2411	2412	2413	2414	2415	2416	2417	2418	2419	2420	2421	2422	2
--	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	---

UNIT 1171063891 22 END-OF-PERIOD ORDINATES, LOG

UNIT	WILDERNESS	77 LINE-OF-THREAT	CREATING	STRENGTH	OF	OF
1	15	15	15	15	15	15
2	15	15	15	15	15	15
3	15	15	15	15	15	15
4	15	15	15	15	15	15
5	15	15	15	15	15	15
6	15	15	15	15	15	15
7	15	15	15	15	15	15
8	15	15	15	15	15	15
9	15	15	15	15	15	15
10	15	15	15	15	15	15
11	15	15	15	15	15	15
12	15	15	15	15	15	15
13	15	15	15	15	15	15
14	15	15	15	15	15	15
15	15	15	15	15	15	15
16	15	15	15	15	15	15
17	15	15	15	15	15	15
18	15	15	15	15	15	15
19	15	15	15	15	15	15
20	15	15	15	15	15	15
21	15	15	15	15	15	15
22	15	15	15	15	15	15
23	15	15	15	15	15	15
24	15	15	15	15	15	15
25	15	15	15	15	15	15
26	15	15	15	15	15	15
27	15	15	15	15	15	15
28	15	15	15	15	15	15
29	15	15	15	15	15	15
30	15	15	15	15	15	15
31	15	15	15	15	15	15
32	15	15	15	15	15	15
33	15	15	15	15	15	15
34	15	15	15	15	15	15
35	15	15	15	15	15	15
36	15	15	15	15	15	15
37	15	15	15	15	15	15
38	15	15	15	15	15	15
39	15	15	15	15	15	15
40	15	15	15	15	15	15
41	15	15	15	15	15	15
42	15	15	15	15	15	15
43	15	15	15	15	15	15
44	15	15	15	15	15	15
45	15	15	15	15	15	15
46	15	15	15	15	15	15
47	15	15	15	15	15	15
48	15	15	15	15	15	15
49	15	15	15	15	15	15
50	15	15	15	15	15	15
51	15	15	15	15	15	15
52	15	15	15	15	15	15
53	15	15	15	15	15	15
54	15	15	15	15	15	15
55	15	15	15	15	15	15
56	15	15	15	15	15	15
57	15	15	15	15	15	15
58	15	15	15	15	15	15
59	15	15	15	15	15	15
60	15	15	15	15	15	15
61	15	15	15	15	15	15
62	15	15	15	15	15	15
63	15	15	15	15	15	15
64	15	15	15	15	15	

W. J. 11.11.11

[illegible]

# HYDROGRAPH ROUTING

## ROUTED OUTFLOW FROM GRANDIN RESERVOIR

ISTAG	ICOHF	IECON	ITAPE	JPLT	JFAT	INAME	ISTAGE	ISUDD
GROUP	1	0	0	0	0	1	0	0

ALL PLANS HAVE SAME

### ROUTING DATA

CLOSS	CLOSS	AVG	IRCS	ISAME	IDPL	IFMP	LSIR
0.0	0.000	0.00	1	1	0	0	0
NSIFS	NSIFL	LAG	AMSKN	X	ISN	SICRA	ISIRAT
1	0	0	0.000	0.000	0.000	-686.	-1

STAGE 684.00 687.00 687.50 688.00 689.00 690.00

FLOW 0.00 120.00 203.00 535.00 1782.00 3758.00

SURFACE AREA= 0. 8. 10.

CAEACILY= 0. 81. 117.

ELEVATION= 653. 686. 690.

CREL	SPWID	COOW	EXFW	ELEV	COUL	CAREA	EXFL
686.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

### DAM DATA

TOPEL	COOW	EXFT	LOMWID
687.5	0.0	0.0	0.

### DAM BREACH DATA

BRWID	Z	ELWA	IFAIL	WSEL	FAILED
60.	.01	656.00	1.50	686.00	687.50

BEGIN DAM FAILURE AT 17.33 HOURS

PEAK OUTFLOW IS 2112. AT TIME 18.06 HOURS

PEAK OUTFLOW IS 244. AT TIME 18.00 HOURS

\*\*\*\*\*

# HYDROGRAPH ROUTING

## CHANNEL ROUTING TO WINCHESTER ROAD

ISTAG	ICOHF	IECON	ITAPE	JPLT	JFAT	INAME	ISTAGE	ISUDD
GROUP	1	0	0	0	0	1	0	0

ALL PLANS HAVE SAME

### ROUTING DATA

CLOSS	CLOSS	AVG	IRCS	ISAME	IDPL	IFMP	LSIR
0.0	0.000	0.00	1	1	0	0	0
NSIFS	NSIFL	LAG	AMSKN	X	ISN	SICRA	ISIRAT
1	0	0	0.000	0.000	0.000	-1.	0

# NORMAL DEFIL CHANNEL ROUTING

QNT(1) QNT(2) QNT(3) ELNUT ELMAX RLNTH SEL  
 .0600 .0400 .0600 450.0 470.0 3000. 08000

CROSS SECTION COORDINATES--STA, ELEV, STA, ELEV--ETC  
 0.00 490.00 105.00 450.00 165.00 470.00 215.00 440.00 250.00 450.00  
 280.00 460.00 330.00 480.00 360.00 490.00

STORAGE 0.00 103.45 126.34 151.83 179.91 210.59 244.29 282.06 323.86 369.97 420.11 470.11

OUTFLOW 0.00 152.35 99499.33 127899.49 160039.01 2852.19 6142.55 11221.28 18526.06 27799.81 379973.34 40157.15 54090.84 443132.03

STAGE 450.00 471.05 482.11 473.16 475.26 477.37 479.47 481.58 483.68 485.79 487.89 489.99 492.09 494.19

FLOW 0.00 152.35 99499.38 127899.42 160039.01 2852.19 6142.55 11221.28 18526.06 27799.81 379973.34 40157.15 54090.84 443132.03

MAXIMUM STAGE IS 455.4

MAXIMUM STAGE IS 452.4

## DEFLECTION ROUTING

### ROUTED OUTFLOW AT WINDHESTER ROAD

INSTAR	ICOMP	IECON	ITATE	JFRT	JFRI	IRAME	ISAGE	INDUD
WINDR	1	0	0	0	0	1	0	0

ALL PLANS HAVE SAME

ROUTING DATA

QLOSS CROSS AVE IRES ISAME IOFI IPHF ISIR

0.0 0.000 0.00 1 1 0 0 0 0

INSTG NSIUL NSIUL LAG AMERN X ISR STORA ISREFAI

1 0 0 0.000 0.000 0.000 -391. -1

STAGE 381.00 382.00 383.00 384.00 385.00 386.00 387.00 388.00 389.00 390.00 391.00 392.00 393.00 394.00 395.00 396.00 397.00 398.00 399.00 400.00 401.00 402.00 403.00 404.00 405.00 406.00 407.00 408.00 409.00 410.00 411.00 412.00 413.00 414.00 415.00 416.00 417.00 418.00 419.00 420.00 421.00 422.00 423.00 424.00 425.00 426.00 427.00 428.00 429.00 430.00 431.00 432.00 433.00 434.00 435.00 436.00 437.00 438.00 439.00 440.00 441.00 442.00 443.00 444.00 445.00 446.00 447.00 448.00 449.00 450.00 451.00 452.00 453.00 454.00 455.00 456.00 457.00 458.00 459.00 460.00 461.00 462.00 463.00 464.00 465.00 466.00 467.00 468.00 469.00 470.00 471.00 472.00 473.00 474.00 475.00 476.00 477.00 478.00 479.00 480.00 481.00 482.00 483.00 484.00 485.00 486.00 487.00 488.00 489.00 490.00 491.00 492.00 493.00 494.00 495.00 496.00 497.00 498.00 499.00 500.00 501.00 502.00 503.00 504.00 505.00 506.00 507.00 508.00 509.00 510.00 511.00 512.00 513.00 514.00 515.00 516.00 517.00 518.00 519.00 520.00 521.00 522.00 523.00 524.00 525.00 526.00 527.00 528.00 529.00 530.00 531.00 532.00 533.00 534.00 535.00 536.00 537.00 538.00 539.00 540.00 541.00 542.00 543.00 544.00 545.00 546.00 547.00 548.00 549.00 550.00 551.00 552.00 553.00 554.00 555.00 556.00 557.00 558.00 559.00 560.00 561.00 562.00 563.00 564.00 565.00 566.00 567.00 568.00 569.00 570.00 571.00 572.00 573.00 574.00 575.00 576.00 577.00 578.00 579.00 580.00 581.00 582.00 583.00 584.00 585.00 586.00 587.00 588.00 589.00 590.00 591.00 592.00 593.00 594.00 595.00 596.00 597.00 598.00 599.00 600.00 601.00 602.00 603.00 604.00 605.00 606.00 607.00 608.00 609.00 610.00 611.00 612.00 613.00 614.00 615.00 616.00 617.00 618.00 619.00 620.00 621.00 622.00 623.00 624.00 625.00 626.00 627.00 628.00 629.00 630.00 631.00 632.00 633.00 634.00 635.00 636.00 637.00 638.00 639.00 640.00 641.00 642.00 643.00 644.00 645.00 646.00 647.00 648.00 649.00 650.00 651.00 652.00 653.00 654.00 655.00 656.00 657.00 658.00 659.00 660.00 661.00 662.00 663.00 664.00 665.00 666.00 667.00 668.00 669.00 670.00 671.00 672.00 673.00 674.00 675.00 676.00 677.00 678.00 679.00 680.00 681.00 682.00 683.00 684.00 685.00 686.00 687.00 688.00 689.00 690.00 691.00 692.00 693.00 694.00 695.00 696.00 697.00 698.00 699.00 700.00 701.00 702.00 703.00 704.00 705.00 706.00 707.00 708.00 709.00 710.00 711.00 712.00 713.00 714.00 715.00 716.00 717.00 718.00 719.00 720.00 721.00 722.00 723.00 724.00 725.00 726.00 727.00 728.00 729.00 730.00 731.00 732.00 733.00 734.00 735.00 736.00 737.00 738.00 739.00 740.00 741.00 742.00 743.00 744.00 745.00 746.00 747.00 748.00 749.00 750.00 751.00 752.00 753.00 754.00 755.00 756.00 757.00 758.00 759.00 760.00 761.00 762.00 763.00 764.00 765.00 766.00 767.00 768.00 769.00 770.00 771.00 772.00 773.00 774.00 775.00 776.00 777.00 778.00 779.00 780.00 781.00 782.00 783.00 784.00 785.00 786.00 787.00 788.00 789.00 790.00 791.00 792.00 793.00 794.00 795.00 796.00 797.00 798.00 799.00 800.00 801.00 802.00 803.00 804.00 805.00 806.00 807.00 808.00 809.00 810.00 811.00 812.00 813.00 814.00 815.00 816.00 817.00 818.00 819.00 820.00 821.00 822.00 823.00 824.00 825.00 826.00 827.00 828.00 829.00 830.00 831.00 832.00 833.00 834.00 835.00 836.00 837.00 838.00 839.00 840.00 841.00 842.00 843.00 844.00 845.00 846.00 847.00 848.00 849.00 850.00 851.00 852.00 853.00 854.00 855.00 856.00 857.00 858.00 859.00 860.00 861.00 862.00 863.00 864.00 865.00 866.00 867.00 868.00 869.00 870.00 871.00 872.00 873.00 874.00 875.00 876.00 877.00 878.00 879.00 880.00 881.00 882.00 883.00 884.00 885.00 886.00 887.00 888.00 889.00 890.00 891.00 892.00 893.00 894.00 895.00 896.00 897.00 898.00 899.00 900.00 901.00 902.00 903.00 904.00 905.00 906.00 907.00 908.00 909.00 910.00 911.00 912.00 913.00 914.00 915.00 916.00 917.00 918.00 919.00 920.00 921.00 922.00 923.00 924.00 925.00 926.00 927.00 928.00 929.00 930.00 931.00 932.00 933.00 934.00 935.00 936.00 937.00 938.00 939.00 940.00 941.00 942.00 943.00 944.00 945.00 946.00 947.00 948.00 949.00 950.00 951.00 952.00 953.00 954.00 955.00 956.00 957.00 958.00 959.00 960.00 961.00 962.00 963.00 964.00 965.00 966.00 967.00 968.00 969.00 970.00 971.00 972.00 973.00 974.00 975.00 976.00 977.00 978.00 979.00 980.00 981.00 982.00 983.00 984.00 985.00 986.00 987.00 988.00 989.00 990.00 991.00 992.00 993.00 994.00 995.00 996.00 997.00 998.00 999.00 1000.00

SURFACE AREA=

CAPACITY=

ELEVATION=

QREL STWID COOL EXW ELEV COUL CAKEA EXIL

381.4 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

PEAK OUTFLOW IS 2000. AT TIME 18.17 HOURS

PEAK OUTFLOW IS 2000. AT TIME 18.00 HOURS



# SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1				SPILLWAY CREST				TOP OF DAM			
ELEVATION				301.10				303.00			
STORAGE				0.				1.			
OUTFLOW				2.				203.			

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF	
					MAX OUTFLOW HOURS	FAILURE HOURS
.21	390.38	2.38	2.	2000.	2.00	18.17
						0.00

PLAN 2				SPILLWAY CREST				TOP OF DAM			
ELEVATION				301.10				300.00			
STORAGE				0.				2.			
OUTFLOW				2.				203.			

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF	
					MAX OUTFLOW HOURS	FAILURE HOURS
.21	300.33	.33	1.	264.	2.17	10.00
						0.00

## STATION HAZARD

PLAN 1				STATION HAZARD			
RATIO				MAXIMUM STAGE-FT			
MAXIMUM FLOW-CFS				TIME			
HOURS				HOURS			
.21	2000.	379.6	10.17				

PLAN 2				STATION HAZARD			
RATIO				MAXIMUM STAGE-FT			
MAXIMUM FLOW-CFS				TIME			
HOURS				HOURS			

1

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....									
ELEVATION		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM		TIME OF	
STORAGE		686.00		686.00		687.50		FAILURE	
OUTFLOW		83.		83.		94.		HOURS	
		0.		0.		203.			
RATIO		MAXIMUM		MAXIMUM		DURATION		TIME OF	
OF		RESERVOIR		STORAGE		OVER JOE		MAX OUTFLOW	
FME		W.S.ELEV		AC-FT		HOURS		HOURS	
.21		687.55		25.		133		18.06	

PLAN 1 *W. of breach*SUMMARY OF DAM SAFETY ANALYSIS - *18-Min. Breach*  
(*Kearney School Reservoir Dam*)

ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	686.00	686.00	687.50
	83.	83.	94.
	0.	0.	203.

RATIO OF PHF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.21	687.54	.04	95.	9196.	.21	17.54	17.33

PLAN 2 *W. of breach*

ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	686.00	686.00	687.50
	83.	83.	94.
	0.	0.	203.

RATIO OF PHF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.21	687.59	.09	95.	264.	2.33	18.00	0.00

## PLAN 1 STATION LB-1

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.21	5879.	450.3	17.50

## PLAN 2 STATION LB-1

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.21	264.	452.4	18.00

# SUMMARY OF DAM SAFETY ANALYSIS

(*at Winchester Dam*)

PLAN 1		INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	PLAN 2		INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
RATIO OF PHF	.21	ELEVATION STORAGE	381.10	381.10	RATIO OF PHF	.21	ELEVATION STORAGE	381.10	381.10
		OUTFLOW	0.	0.			OUTFLOW	0.	0.
RATIO OF PHF	.21	MAXIMUM RESERVOIR W.S.ELEV	391.35	3.	RATIO OF PHF	.21	MAXIMUM RESERVOIR W.S.ELEV	391.35	3.
		MAXIMUM DEPTH OVER DAM	3.35	5402.			MAXIMUM DEPTH OVER DAM	3.35	5402.
RATIO OF PHF	.21	MAXIMUM STORAGE AC-FT	3.	50	RATIO OF PHF	.21	MAXIMUM STORAGE AC-FT	3.	50
		MAXIMUM OUTFLOW CFS	5402.	17.50			MAXIMUM OUTFLOW CFS	5402.	17.50
RATIO OF PHF	.21	TIME OF FAILURE HOURS	0.00	0.00	RATIO OF PHF	.21	TIME OF FAILURE HOURS	0.00	0.00
		MAX OUTFLOW HOURS	18.00	18.00			MAX OUTFLOW HOURS	18.00	18.00

## PLAN 1 STATION HAZARD

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.21	5342.	376.6	17.50

## PLAN 2 STATION HAZARD

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.21	264.	372.1	18.00



NOT AVAILABLE AT THIS TIME

END